

EXHIBIT "F"



VIA FACSIMILE (516) 869-8765

August 14, 2001

Ed Digioia
Genatt Associates, Inc.
3333 New Hyde Park Road
New Hyde Park, NY 11042

Dear Ed:


Enclosed please find the report on the boiler problem. Despite the memo, the boiler may not be repairable and we are suffering business interruptions. We could default on about \$1 million in sales unless we re-establish the steam from a boiler. A new boiler including installation may exceed \$25,000 in cost. We would like an inspection to determine the cause of the boiler's failure ASAP.

Sincerely,

A handwritten signature in dark ink, appearing to read "Steven A. Schulman", written over a horizontal line.

Steven A. Schulman
President

SAS:lss
Enclosure



Mafcote Inc. • 108 Main Street • Norwalk CT 06851
phone - (203) 847-8500 • fax - (203) 849-3177

Case No. 1:04cv853
M000152

Miami Wabash Paper Company, Inc.
413 Oxford Road
Franklin, Ohio 45005
Phone: 937-746-6451
Fax: 937-746-2139

FAX TRANSMITTAL

NUMBER OF PAGES INCLUDING THIS SHEET: _____ DATE: 8-13-01

TO: SAS

FAX NO: HQ

FROM: BK

☒ Urgent ☒ For Your Review ☐ Reply ASAP ☐ Please Comment

REMARKS:

Steve,

- ① The Boiler ruptured on 7/26/01
- ② The reason is either mud or scale buildup
- ③ Mud & scale was removed 1.8 months ago for the first time when I had boiler serviced. It had not been service since installation. Service by Combustion Equipment.
- ④ Repair inspection will be in 8-14-01. Repair cost projected to be \$5,000.00

Combustion Equipment Co., Inc.

22 E. Nottingham Road
 Dayton, OH 45405

Proposal

Phone 937-228-5414 Fax 937-277-5381

DATE Proposal #

To

8/9/01 200264

Miami Valley Paper Company, Inc.
 413 Oxford Road
 Franklin, OH 45005

Price Good Till 10/9/01

TERMS

Net 30

Attn: Bob K.

DESCRIPTION	TOTAL
We are pleased to quote you on the following replacement boiler for your plant.	0.00
To furnish one (1) Columbia CT15 vertical steam gas fired boiler. We will remove old boiler, install new, tie into existing stack, steam header, feedwater and blowdown system. Fire, setup, and 1 year warranty on material and labor.	24,749.00
Any other repairs required by inspectors, to be extra after approval first.	0.00
Freight is F.O.B. Factory. Approx. shipping time is 1-2 weeks	0.00
Please add any tax that may be required.	0.00
Thank you for the opportunity of serving you as we have in the past.	
TOTAL	\$24,749.00

Accepted _____

Date _____

SIGNATURE

Boysi Flanagan

PAGE.003

NO. 800-UP-3-ITU.

PICKEREL BROS. INC.

801 E. FERRY ST. DAYTON, OHIO 45402
WHOLESALE DISTRIBUTORS

Y 252327

TEMPERATURE:
IN SUN/SHADE:
MATERIAL: DRY...

DRAFT
RECEIVED

SOLD
TO

MIAMI VALLEY PAPER COMPANY.

413 OXFORD ROAD

FRANKLIN, OHIO

53059

2005

१३

2025-56-070 HK

✓ 107-1217-54

401495. 1080 4. 1976 6. 1976

YOUR ORDER NO.	SHIPMENT	FOB	JOB	SALES	DATE SHIPPED
----------------	----------	-----	-----	-------	--------------

6902

برقیہ کی

QUANTITY			DESCRIPTION	UNIT	RATE	AMOUNT
ORDERED	RECEIVED	IN STOCK				

1

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

10-11-68

15

KUNDY

HP HRT 30/10/12 12:00

463 540-1 2-10

50 x 6.

John D. +	Kelley 1st
-----------	------------

L-5837

File # 1343

401 4th Class

20.

Installation
not included

REC'D	TERMS: 2% WITH DISC ON THIS ACCOUNT ONLY	MATERIAL TOTAL	154300
-------	---	-------------------	--------

We hereby certify that these goods were produced in compliance with all applicable requirements of sections 6, 7, and 12 of the Fair Labor Standards Act as administered and enforced by the United States Department of Labor, District under section 14 thereof.

PRICES SUBJECT TO CHANGE WITHOUT NOTICE

IN CONFORMANCE WITH
EXECUTIVE ORDER 12812

MATERIAL
TOTAL

15430 D

✓FREIGHT

TAX

TOTAL

AUG 13 '01 18:04 FRL MIAMI VALLEY PAPER TO PORATE# PAGE.004
HIS.13.0001 2.0001 FLOWEL DRS. INC.

LATIMER BOILER MFG. CO.

1411 9TH STREET SW
P.O. Box 1527
Cedar Rapids, IA 52406
319-388-0778

SOLD TO:

Pickrel Bros. Inc.
901 South Perry
Dayton, OH 45402
513/461-5960

SHIP TO NOTIFY OFFICE BEFORE SHIPPING

Miami Valley Paper Co.
413 Oxford Road
Franklin, OH 45005

MARK: P.O. #V252327

PROMISED DATE

Tue 3/3/95

ACCOUNT NO.

DATE RECEIVED: 2/2/95

DATE SHIPPED:

TERMS: net 30 days

INV. NO.:

SALESPERSON: fax

SHIP VIA

best way

☐ PPD☒ COL☐ COD

FOB SHIPPING POINT: Cedar Rapids, IA

QTY.	PART NO.	DESCRIPTION	UNIT PRICE	TOTAL LIST EXTENSION	DISCOUNT %	TOTAL NET AMOUNT
1		35 H.P. gas-fired POWERPLUS with "X" equipment Standard controls RK7890 flame safeguard w/ runner pilot Safety shut-off valve on thermocouple pilot 2nd safety shut-off solenoid gas valve Motorized gas valves to have fixed orifice in bypass line, drill <u>1/8"</u> Motorized valve to stack end to have end switch to energize valve opposite stack end Furnish lever handle gas cock on gas inlet Maxitrol 3/8" Model 325-3 gas pressure regulator on pilot gas line U/L label CSB-1 B2V: 1050 S.G.: .61 Drill size: 9/32 S.V.: (2) 1" - 150#				

 RECEIVED
 AUG 07 1995
 PICKREL BROS. INC.
 DAYTON, OHIO

SPECIAL INSTRUCTIONS:

CALL DAY 513/461-5960 24 HOURS BEFORE SHIPPING

GROSS TOTAL

TAX (if applicable)

SHIPPING & HANDLING

MISC. CHARGES

BALANCE DUE